

Undertaking 68

Re Joint Utilities Meeting Minutes, May 15, 2013

Undertake to check if the long-term maintenance plan for the Long Harbour transmission line and terminal station was provided to Vale and any updates.

Per item 1 of the 2013 Joint Utilities Meeting action list, the following maintenance plan for TL208 was provided to Vale:

Maintenance Plan for TL208

A portion of TL208 is new (extension to the Vale terminal station). At this time replacement of the line or major rebuild work is not in the 20 year plan. Current preventive maintenance work is as follows:

1. Full climbing inspection of 10% of the line per year.
2. Helicopter patrol 2 times per year including infrared inspection.
3. Ground patrol inspection as required.
4. Any corrective maintenance required as a result of preventive maintenance is carried out at the time of inspection or as soon as an equipment outage can be arranged.