

1 Q. On page 5 of the report it is noted that the transformer can be configured for two
2 low voltage levels. Please confirm that the transformer can deliver full output at the
3 46/12.5kV rating.

4

5

6 A. According to the nameplate on QZT-T2, the transformer has a winter rating (at 0°C)
7 of 10/13.3/16.7 MVA at 12.5 kV. Hydro is not aware of any reason why the
8 transformer cannot deliver full output at the 46/12.5 kV rating.