## Page 1 of 1

Q.	On page 5 of Hydro's Replacement of Equipment Resulting from Sunnyside T1
	Transformer, it is stated that:
	"However, it must be noted that a fault on Sunnyside T4 would still require
	operation of five circuit breakers to isolate the transformer."
	Has Hydro tested the operation of the Sunnyside T4 transformer protection and
	control system since the January 2-8, 2014 electrical system events? If so, what
	were the results?
A.	Hydro has not yet completed testing of T4 transformer protection and control
	system, but will complete this testing during a scheduled T4 outage planned for July
	22, 2014.