## Page 1 of 1

1	Q.	On Page 20 of 20 to Appendix B of Hydro's Replace T5 Tap Changer Western Avalon
2		Terminal Station report, ABB recommends adding a diaphragm to the transformer's
3		oil conservator. Is Hydro adding a diaphragm to the conservator? If not, please
4		explain.
5		
6		
7	A.	Hydro is reviewing this recommendation and has received some preliminary
8		information from the Original Equipment Manufacturer, CG Global. Further
9		discussion and information exchange is required and a decision is expected by July
10		31, 2014.