Page 1 of 1

1 Q. Please refer to Appendix B. Was the then proposed new refinery near Pipers Hole 2 represented in the study? 3 4 5 A. The then proposed new oil refinery near Pipers Hole was not included in the 6 stability studies summarized in Appendix B. Given the transmission line and 7 roadway congestion near the Sunnyside Terminal Station location, and the fact that 8 west of the Sunnyside Terminal Station the existing 230 kV transmission lines 9 (TL202 and TL206) are bounded on the north and south sides of the right-of-way by 138 kV transmission lines (TL219 and TL212), Hydro selected the Piper's Hole 10 11 location as a preliminary site for the proposed series compensation stations for 12 TL202 and TL206 as TL219 and TL212 would not impede access to the 230 kV 13 transmission lines in this area. 14 15 In addition, the SNC-Lavalin stability studies provided in Appendix C10 did not 16 include the proposed oil refinery near Pipers Hole.