| 1  | Q. | Project C-13, Upgrade North Cut-Off Dam Access Road – Bay d'Espoir                        |
|----|----|---|
| 2  |    | At page 6 of the report filed at Volume I, Tab 5, Hydro states that "When                 |
| 3  |    | attempting to conduct repairs on damaged components of the vehicle, employees             |
| 4  |    | are often placed in situations in which there is an increased risk for injury. The        |
| 5  |    | nature of the typical repair presents a risk of injury by way of heavy lifting, crushing, |
| 6  |    | burns, and abrasions". Please provide a full account of any such injuries incurred or     |
| 7  |    | experienced by Hydro personnel in the last five (5) years, including date and nature      |
| 8  |    | of injury suffered.   |
| 9  |    |   |
| 10 |    |   |
| 11 | A. | Fortunately, there have been no reported personnel injuries in the past five years        |
| 12 |    | due to these hazards. A SWOP review revealed the following near miss incidents on         |
| 13 |    | Hydro's access roads where the potential for injury was identified:                       |
| 14 |    | • Snowmobiles hitting snow covered rocks – January 17, 2009 and March 30,                 |
| 15 |    | 2009;   |
| 16 |    | • Vehicle slid off road – March 19, 2008, July 16, 2008 and February 11, 2013;            |
| 17 |    | and   |
| 18 |    | • Oil leaking from base pan (or rear end), vehicle not operational – June 6,              |
| 19 |    | 2008, July 24, 2008, August 14, 2008, and November 5, 2008.                               |