1	Q.	Project C-30, Install Cold-Reheat Condensate Drains and High Pressure Heater Trip
2		Level Unit 3 – Holyrood
3		Have there been any incidents of water damage to the steam turbine in Unit 3
4		thought to be a consequence of water in the cold reheat lines? If so, please provide
5		details of any incidents.
6		
7		
8	A.	There have been no incidents of water damage to the steam turbine in Unit 3
9		thought to be a consequence of water in the cold reheat lines.