

1 Q. C-3; Volume I, Tab 1: Rewind Stator Unit 3 – Bay D’Espoir, page A70, clause 4.4:
2 the AMEC report states that: *“During the rewind of the generator of either Unit*
3 *#1 or Unit #3, there will be no redundancy for the station services for the Plant. It*
4 *would be worthwhile to consider an alternate power source to restore the*
5 *redundancy in these power supplies during the outages.”*

6 How will Hydro address this recommendation in 2014 during the rewind of the Unit
7 #3 stator?

8

9

10 A. Please see response to PUB-NLH-7.