

1 **B-23 Replace Fuel Piping, \$529,800**

2 Q. What similarities exist to cause the conclusion that Stephenville would be in
3 the same condition as Hardwoods? Are there any differences?

4

5

6 A. Please refer to response IC-13 NLH.