

1 Q. **Re: Page 24, Table 1**

2 Given the issues over the last couple of years with Penstock No. 1 and Penstock No.
3 2 along with the recent discovery of potential similar issues with Penstock No. 3,
4 has Hydro given any consideration to increasing the DAFOR for the Bay d’Espoir
5 hydraulic units? If not, please provide the rationale for not raising the DAFOR
6 estimate.

7

8

9 A. Please refer to Hydro’s response to PUB-NLH-012 for more information regarding
10 the Bay d’Espoir plant Derated Adjusted Forced Outage Rate (DAFOR).