

- 1 **Q. (Reference Application, 5.1 Port Union Building Replacement, page 8) It is**
2 **stated “Some wiring is original cloth insulated type which is a suspected**
3 **asbestos hazard based on similar wire observed in other locations.” Has NP**
4 **inspected all of its facilities to determine if there is wiring suspected to be an**
5 **asbestos hazard? Is it an environmental requirement that wiring be removed**
6 **if suspected to be an asbestos hazard?**
7
- 8 A. Newfoundland Power periodically inspects its facilities to determine if hazards are
9 present. Asbestos surveys are completed in cases where the presence of asbestos is
10 suspected. It is not an environmental requirement that wiring be removed if suspected
11 to be an asbestos hazard.