

**PUB 1.0**

**(RE: p. 9 & 10 of 82)                      Hydro Plants Facility Rehabilitation (\$2,345,000)**

**PUB 1.2**

**Q.        Provide copies of any assessments or reports prepared regarding dam rehabilitation at Seal Cove, Blackwoods and Whirl Pond.**

A.        Attached are copies of the assessments and reports regarding dam rehabilitation at Seal Cove, Cape Broyle/Horsechops (Blackwoods section only), and Port Union (Whirl Pond section only):

Seal Cove – Dam Safety Inspection Reports

1. October 1999 (prepared by Newfoundland Power), Attachment A.
2. November 2001 (prepared by Newfoundland Power), Attachment B.

Seal Cove – Dam Safety Inspection Checklists

3. February 2000 (prepared by Newfoundland Power), Attachment C.
4. October 2000 (prepared by Newfoundland Power), Attachment D.
5. December 2000 (prepared by Newfoundland Power), Attachment E.
6. June 2001 (prepared by Newfoundland Power), Attachment F.

Blackwoods– Dam Safety Inspection Reports

1. March 1999 (prepared by Newfoundland Power), Attachment G.
2. November 2001 (prepared by Newfoundland Power), Attachment H.

Whirl Pond– Dam Safety Inspection Reports

1. November 1999 (prepared by Newfoundland Power), Attachment I.
2. December 2000 (prepared by Newlab Engineering), Attachment J.

Whirl Pond – Dam Safety Inspection Checklists

3. April 2000 (prepared by Newfoundland Power), Attachment K.
4. August 2000 (prepared by Newfoundland Power), Attachment L.
5. June 2001 (prepared by Newfoundland Power), Attachment M.
6. November 2001 (prepared by Newfoundland Power), Attachment N.