

1 **Re: Replace Cooling Water System on Units 3 and 4**

2 Q. When was the photo provided as Figure 1 taken and what unit did the pipe  
3 come from?

4

5

6 A. The photo was taken in August 2006. It is of a section of fouled pipe which  
7 was removed in 2005 from the cooling water system for Bay d'Espoir  
8 generating Unit 1.