

1 Q. Provide a copy of all engineering assessment documentation that was available in
2 2012 that shows that it was not practical to repair the gas turbine that had been
3 used to provide black start capability to the Holyrood Thermal Generating Station
4 since 1970 (the “Holyrood Gas Turbine”).
5
6

7 A. The condition assessment prepared by AMEC and issued to Hydro on December 19,
8 2011 included a comparative analysis of options and recommended an option other
9 than repairing the existing gas turbine at Holyrood. Please see NP-NLH-022 Rev. 1,
10 Attachment 1, Sections 4 to 6.