

1 **Q. *Re: Tab 5.1, Company Building Renovations***

2
3 **Why has mildew been allowed to build up on the warehouse's exterior siding as**
4 **shown on Figure 7? Does anyone have responsibility for removal of such mildew at**
5 **the warehouse facility?**

6
7 **A.** The mildew on the outside of the building was last removed about 4 years ago. After that
8 time the growth redeveloped again fairly quickly. The ground in this area is poorly
9 drained and damp most of the time resulting in the formation of this growth. As part of
10 the project these drainage issues will be addressed to prevent this from re-occurring.