

1 **Q. *Re: Tab 5.1 - 2013 Company Building Renovations***

2
3 **As regards Figures 7, 8, 9 and 10, showing the “Typical Bathroom Finishings” and**
4 **“Typical Bathroom Fixtures”, it is not evident what the problem is with these**
5 **washroom facilities. Please explain what Newfoundland Power intended to convey**
6 **by providing photos of its bathroom facilities.**

7
8 **A.** Photographs of the bathroom facilities are representative of the original 1960s and 1970s
9 vintage finishes and fixtures that are typical in all eight bathrooms at the Kenmount Road
10 building. The washroom components are worn and deteriorated and upgrades are
11 required to plumbing and ventilation, which is difficult to illustrate through photographs.