

1 Q. **2015 Capital Projects 500,000 and Over**

2 Purchase Spare Transformer, page C-25:

3 Hydro outlines that its condition assessment tool provides a ranking for all
4 transformer units. The results show that T1 displays signs of deterioration. When
5 was the assessment of the T1 completed?

6

7

8 A. The assessment referenced in this report was for Degree of Polymerization (DP) and
9 this was completed in 2010 and recorded to be 628, while in 2014 it was recorded
10 to be 603.