

1 Q. Reference: Refurbish Generation Unit – Snook’s Arm, Volume I, Section D,
2 Page D-57

3 *“In 2003 an internal visual assessment was performed on the electrical equipment*
4 *at Snook’s Arm.”*

5 Has Hydro completed any other assessment of the Snook’s Arm electrical
6 equipment since this 2003 assessment?

7

8

9 A. Hydro has not completed any other assessment of the Snook’s Arm electrical
10 equipment since this 2003 assessment.