

1 **Re Page B-89:**

2 Q. Describe in detail the use to which this building has been put and provide
3 specifics of each such utilization in the last ten years, including the length of
4 time on each occasion that the building was occupied.

5

6

7 A. This building was utilized in the mid-eighties during the repair of damage to
8 transmission lines as a result of ice accumulation. Twelve structures had
9 collapsed and needed to be replaced completely whereas others needed to
10 be modified and/or repaired. Line crews used this camp and one other camp
11 in the area for approximately three months. This camp has not been used
12 since the mid-eighties. The frequency and duration of use of the camp are
13 not the main criteria by which its need should be judged. This is primarily a
14 survival structure, required to ensure the safety of line crews which could
15 become stranded in this remote area during a storm.