

1 Q. **Re 2011 Capital Plan - Individual Capital Projects:**

2 **Project B-28, Upgrade Generating Station Service Water System-Cat Arm:** What
3 has been the operating experience with fouling of the stainless steel piping installed
4 at Granite Canal?

5

6

7 A. There have been no operating problems associated with fouling of the stainless
8 steel piping installed at Granite Canal Generating Station during its seven years of
9 operation. Trending of the flow rates and bearing temperatures indicate that there
10 is little or no fouling present.