



1 Q. **Fuel Oil Storage Facility:** With reference Figures 1 through 4 of the July 2011 Hydro
2 report supporting this Project, provide the same Figure representation for Fuel
3 Storage Levels in 2006, 2007, 2008, 2009, 2010 and to the extent available in 2011.

4
5
6 A. Following are figures representing the fuel storage levels from January to April in
7 2006, 2007, 2008, 2009, 2010 and 2011. As is indicated by the total available
8 storage in the charts, No. 2 tank was out of service from January 16, 2007 through
9 to March 27, 2009 due to thermowell and suction valve failures.




Holyrood Fuel Storage Levels 2006

Holyrood (HTGS) Stack Breeching and Fuel Tank Refurbishment




Holyrood Fuel Storage Levels 2007




Holyrood Fuel Storage Levels 2008

Holyrood (HTGS) Stack Breeching and Fuel Tank Refurbishment




Holyrood Fuel Storage Levels 2009



Holyrood Fuel Storage Levels 2010

Holyrood (HTGS) Stack Breeching and Fuel Tank Refurbishment



Holyrood Fuel Storage Levels 2011