

1 Q. **Unit 1 Stack Breaching:** With reference to section 4.3 of the July 2011 Hydro report,
2 what would be the CPW of Alternatives 1, 3 and 7 if the annual O&M cost was
3 estimated to be the average of the 11-year maintenance cost history for Unit 1
4 calculated without inclusion of the floor replacement cost incurred in 2006?

5

6

7 A. The CPW of Alternatives 1, 3, and 7 without the inclusion of the floor replacement
8 cost incurred in 2006 has been included in the table below:

| Alternative | CPW (\$) |
|-------------|-----------|
| 1 | 4,060,220 |
| 3 | 2,074,894 |
| 7 | 2,098,194 |

9 As shown in the response to PUB-NLH-5, Alternative 2 remains the least cost
10 alternative.