

1 **Q. E-66; Volume I, Tab E: Replace DC Distribution Panels and Breakers – Holyrood:**

2 Please provide details of the role that the failure of Unit 1 at the Holyrood Thermal
3 Generation Station at Holyrood and the resulting January 2013 outage played in the
4 determination that the DC distribution panels and breakers should be replaced at
5 this time.

6

7

8 **A.** The January 11th event had no role in determining the requirement to replace the
9 DC panels and breakers. The necessity for this project was determined before
10 January 11, 2013.