

1    Q.    Indicate the specific dates on which the photographs included in the answer  
2           to IC8-NLH were taken and for what purpose they were taken.

3

4

5    A.    Picture 1 – July 13, 06

6           Picture 2 – July 13, 06

7           Picture 3 – July 13, 06

8           Picture 4 – August 17, 06

9           Picture 5 – August 17, 06

10          Picture 6 – August 17, 06

11

12           These pictures were taken for the purpose of showing the typical state of  
13           corrosion that can be found through out this 40-year-old cooling water piping  
14           system. Pictures 1 to 3 were taken during an inspection of the cooling water  
15           piping system to determine the state of corrosion present.