

- 1 **Q. (Reference CA-NP-099) Please confirm that none of the outages shown in**  
2 **Table 1 resulted in customer service interruptions.**  
3
- 4 A. It is confirmed. Transmission Line 146L forms part of the Central Newfoundland 138kV  
5 looped transmission system. As such, none of the outages shown in Table 1 resulted in  
6 a service interruption to customers. However, as described in Newfoundland Power's  
7 *2024 Capital Budget Application, report 3.1 2024 Transmission Line Rebuild,*  
8 Transmission Line 146L is critical to the reliable operation of the Central Newfoundland  
9 138kV system.